



Demonstration Box

WARNING!

Never leave box unattended while plugged in. Do not allow box temperature to exceed 140°F.

Handle may become hot after extended use at high temperatures.

- Replace Light Bulb with type GU10 base, 50W max.
- Replace Batteries with type LR44 or equivalent.

To Open: Gently slide faceplate to the right.

